Durability of European oak (spp.) in ground contact – A case study on fence posts in service

Christian Brischke, Heiner Rolf-Kiel

► To cite this version:

Christian Brischke, Heiner Rolf-Kiel. Durability of European oak (spp.) in ground contact – A case study on fence posts in service. European Journal of Wood and Wood Products, 2009, 68 (2), pp.129-137. 10.1007/s00107-009-0364-7 . hal-00568246

HAL Id: hal-00568246

<https://hal.science/hal-00568246>

Submitted on 23 Feb 2011

HAL is a multi-disciplinary open access archive for the deposit and dissemination of scientific research documents, whether they are published or not. The documents may come from teaching and research institutions in France or abroad, or from public or private research centers.

L'archive ouverte pluridisciplinaire **HAL**, est destinée au dépôt et à la diffusion de documents scientifiques de niveau recherche, publiés ou non, émanant des établissements d'enseignement et de recherche français ou étrangers, des laboratoires publics ou privés.

Draft Manuscript for Review

**Durability of European oak (*Quercus* spp.) in ground contact
– A case study on fence posts in service**

Journal:	<i>Holz als Roh- und Werkstoff</i>
Manuscript ID:	HRW-09-0034.R1
Manuscript Type:	ORIGINALARBEITEN / ORIGINALS
Date Submitted by the Author:	05-Jun-2009
Complete List of Authors:	Brischke, Christian; Leibniz University Hannover, Institute of Vocational Sciences in the Building Trade Rolf-Kiel, Heiner; Leibniz University Hannover
Keywords:	Decay, dimension, European use class 4, service life prediction, soil type, water holding capacity, white rot

1 **Durability of European oak (*Quercus* spp.) in ground contact – A case study**
2
3 **on fence posts in service**
4

5
6 C. Brischke*, H. Rolf-Kiel
7

8
9 *corresponding author

10 ¹Dr. Christian Brischke,
11 Leibniz University Hannover, Institute of Vocational Sciences in the Building Trade,
12 Herrenhäuser Str. 8, D-30419 Hannover, Germany,
13 E-mail: brischke@ibw.uni-hannover.de
14
15

16
17
18 **Abstract**

19 The durability of European oak (*Quercus* spp.) is under debate for a long time. In contrast to
20 its classification as “durable” timber species according to EN 350-2 (CEN 1994), results from
21 different comparative studies have clearly shown a lower durability, especially for in-ground
22 exposures. To highlight this conflict more detailed, a case study on oak fence posts, which
23 had been in service for 5, 10, 20, 30, and 60 years, was carried out. The posts were examined
24 in terms of decay type and intensity, remaining cross section, wood moisture content, and
25 different characteristics of the adjacent soil. The durability of the oak posts was affected by
26 high variation. Posts prematurely failing after only five years were found as well as posts still
27 serviceable after 60 years. Different findings of the study have the potential to increase the
28 understanding of durability aspects in the future and might be considered for calibration and
29 adaption of field and laboratory tests methods in the future: The ground line turned out to be
30 not the most severe exposure for posts, although it is generally assumed to be. Furthermore,
31 no significant negative impact of remaining sapwood portions on the durability of the
32 heartwood was found, but the important role of radial cracks for the initiation of decay
33 became apparent. In this regard further potentially important factors for the in-ground
34 durability are size and shape of timber components.
35
36
37
38
39
40
41
42
43
44

45 **Die Dauerhaftigkeit Europäischer Eiche (*Quercus* spp.) im Erdkontakt –**
46 **Eine Fallstudie an Weidezaunpfählen im Gebrauch**
47
48
49

50
51 **Zusammenfassung**
52
53
54
55
56
57
58
59
60

Die Dauerhaftigkeit von Eichenholz (*Quercus* spp.) wird seit langer Zeit kontrovers diskutiert. Während es nach EN 350-2 (CEN 1994) als “dauerhaft” (Dauerhaftigkeitsklasse 2) eingestuft wird, haben Ergebnisse vergleichender Studien eine deutlich geringere Dauerhaftigkeit belegt, insbesondere bei Exposition mit Erdkontakt. Um diesen Widerspruch näher zu betrachten, wurde eine Fallstudie an Eichenzaunpfählen durchgeführt, die sich bereits seit 5, 10, 20, 30 und 60 Jahren im Gebrauch befanden. Die Pfähle wurden in Bezug auf Art und Intensität von Fäulnis, Restquerschnitt, Holzfeuchte und verschiedener Charakteristika des umgebenden Bodens untersucht. Die Dauerhaftigkeit der Eichenpfähle war durch eine hohe Variation gekennzeichnet. Frühausfälle nach nur fünf Jahren wurden ebenso beobachtet wie Pfähle, die nach 60 Jahren immer noch gebrauchstauglich waren. Verschiedene Erkenntnisse aus der Studie tragen zu einem besseren Verständnis der Dauerhaftigkeit von Eichenholz im Erdkontakt bei und ließen sich zur Kalibrierung und Anpassung von Labor- und Freiland-Prüfmethoden berücksichtigen. So stellte sich die als besonders kritisch erachtete Boden-Luft-Zone nicht als die Zone mit der stärksten Befallsintensität heraus. Weiterhin ließ sich kein signifikanter negativer Einfluss von Splintholzanteilen auf die Gebrauchsdauer der Pfähle nachweisen; die besondere Rolle radialer Risse in den Pfählen als Ausgangspunkt für Fäulnis wurde hingegen deutlich. In diesem Zusammenhang sei ebenfalls auf die Bedeutung von Dimensionierung und Form von Bauteilen auf die Dauerhaftigkeit im Erdkontakt hingewiesen.

Formatted: Bullets and Numbering

1 Introduction

The timber of European oak (*Quercus robur* L. and *Q. petraea* Liebl.) is an appreciated building material and therefore it has been used since centuries. Its suitability for outdoor applications derives from its proverbial durability (Kollert 1991), and in fact it is classified as “durable” species (durability class 2, DC 2) according to EN 350-2 (CEN 1994). Thus, it is one of the most durable domestic wood species in Europe besides Black locust (*Robinia pseudoacacia* L., DC 1-2) and Sweet chestnut (*Castanea sativa* Mill., DC 2). Archaeological oak findings from Roman times (Haneca et al. 2005) as well as numerous half-timbered oak houses, which have still remained since the 16th century (Schepers 1994) also point to an outstanding durable timber species.

On the other hand, several authors reported on laboratory results indicating an inter-specific variability of European oak durability with remarkable percentages of moderately durable, poorly durable and not durable timber (Ayadi et al. 2001, Aloui et al. 2004, Guilley et al.

2004, Humar et al. 2008). Results from soil bed tests against soft rotting and other soil-inhabiting micro-organisms also led to lower durability classes, e.g. DC 3-4 as reported by Van Acker et al. (2003). Comparative studies by Brischke et al. (2009) revealed significant discrepancies between results from different laboratory tests, field tests and the current European normative durability classification. In laboratory soil box tests as well as in in-ground field tests according to EN 252 (CEN 1990), oak was found to be non durable (DC 5), and even exposed above-ground in double layer tests it was only classified as less durable (DC 4). Soil box tests with different terrestrial microcosms gave a strong indication on the results to be expected in the field, because of similar types of decay organisms involved (i.e., mainly soft and white rot causing fungi). In contrast, laboratory resistance tests with basidiomycete monocultures were misleading as they suggest classifying European oak as a “very durable” timber. Though the various field studies showed that the durability of European oak heartwood seems to be fairly overestimated, they could not explain where this overestimation derives from.

Therefore, in this case study, oak posts, which had been in service between 5 and 60 years, were surveyed to obtain more information on the durability of oak timber under real life conditions. The posts were sampled at five different sites in North Rhine-Westphalia, Germany and assessed with respect to decay and wood moisture content. Furthermore, the in-use conditions were examined in terms of different soil parameters.

Formatted: Bullets and Numbering

2 Materials and Methods

2.1 Sites and sampling of the posts

Oak fence posts were examined at five sites (feedlots) in the rural district Gütersloh, North Rhine-Westphalia, Germany, representing previous service lives of 5, 10, 20, 30, and 60 years. Round posts were included as well as splitted and double splitted posts. The geographic characteristics of the sites, and the corresponding number and type of fence posts sampled are summarized in Table 1.

The posts were carefully pulled out of the ground using a vertical hydraulic elevating device. Total length of the posts and depth of burying were determined, afterwards adherent soil was removed. For determination of remaining cross sections and wood moisture content, discs of 20 mm thickness were cut out of the posts at four different sections planes (30 cm above ground, at the ground line, 30 cm below ground, and 60 cm below ground, see Fig. 1).

2.2 Determination of remaining cross section

The remaining cross section was determined in all four sections of all sampled posts. Therefore, the wooden discs were sanded, scanned and the areas of the original heartwood section ($A_{original}$) as well as the remaining undecayed heartwood section ($A_{existing}$) calculated using “Adobe Photoshop CS3” (Fig. 2). As the original heartwood sections were unknown due to different cross shapes and degrees of conicity of the posts, it was reconstructed considering number, width and course of the annual rings in the different section planes. The non-durable sapwood was not considered.

The percentage of the remaining cross section $A_{remaining}$ was calculated as follows:

$$A_{remaining} = \frac{A_{existing}}{A_{original}} \cdot 100 [\%]$$

In addition, the prevailing type of decay (white rot, brown rot, or soft rot) was identified for each post and section plane according to EN 15083-2 (CEN 2005).

2.3 Determination of wood moisture content

The wood moisture content was determined according to DIN 52183 (DIN 1977) for the inner and outer part of the heartwood from each section plane at five posts per site. The specimens were weighed (m_u), dried at 103 ± 2 °C until constant mass, and weighed again (m_0). The wood moisture content (MC) was calculated as follows:

$$MC = \frac{(m_u - m_0)}{m_0} \cdot 100 [\%]$$

2.4 Determination of soil parameters

The soil at the different sites was sampled close to those posts which were used for wood moisture measurements to determine its moisture content, water holding capacity, and pH-value. Around each post, four single samples were taken using a sampling tube, which allowed sampling in different depths (0 to -10 cm, -25 to -35 cm, and -55 to -65 cm) corresponding to the section planes 0 cm, -30 cm, and -60 cm. Prior to the analysis, the four single samples were merged to obtain one homogenous and representative total probe per section plane.

To determine the soil moisture content (MC_{soil}) 80-100 g moist soil were weighed (m_u), dried at 103 ± 2 °C till constant mass, and weighed again (m_0). The soil moisture content was calculated as follows:

$$MC_{soil} = \frac{(m_u - m_0)}{m_0} \cdot 100 [\%]$$

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

The water holding capacity (WHC) was determined according to ISO 11268-2 (ISO 2000). Therefore, the soil samples were air dried, pounded in a mortar, sieved (mesh size: 2 mm), and put into plastic tubes ($\varnothing = 40$ mm, $l = 10$ cm). The bottom of the tubes was covered with a synthetic grit and a filter paper (MN 640 W, Macherey Nagel, Düren). The filling height was 7 cm. The tubes were dipped in deionised water for 12 h to obtain water saturation of the substrate. Afterwards the tubes were put on a water saturated sand bath for 2 h to drain off. To determine the WHC of the substrate it was weighed (m_u), dried at 103 ± 2 °C till constant mass, and weighed again (m_0). The WHC was calculated as follows:

$$WHC = \frac{(m_u - m_0)}{m_0} \cdot 100 [\%]$$

The pH-value of the soil samples was determined in deionised water as well as in 0.01 molar CaCl_2 -solution according to ISO 10390 (ISO 2005). After suspending 10 g of each air dried and sieved sample for 2 h in 25 ml of the respective liquid, the pH was measured with a pH-meter (pH-Checker, Hanna Instruments).

3 Results and discussion

3.1 Remaining cross section

Regarding the mean remaining cross section as a measure for the degree of destruction of the posts, a high variation was observed between the different section planes as well as between the different sites and previous service lives, respectively (Table 2). The mean minimum remaining cross section decreased from site 1 (84.9 %) to site 3 (34.96%) with increasing previous service life, but was higher at site 4 (42.9%) after 30 years and at site 5 (40.9%) after at least 60 years in service.

Remarkable differences between the differently old posts became obvious when the posts were grouped according to their remaining cross section independent from the section plane. In Table 3 only the section with the smallest remaining cross section was considered: 40 % of the posts at site 1 had already lost more than 10% of their cross section due to decay, although they had been in service for only 5 years. In contrast, more than half of the posts at site 5 retained more than 50% of their cross section after at least 60 years in service.

Formatted: Bullets and Numbering

Furthermore it became evident that the section plane with the smallest mean remaining cross section was not the same for the different sites (section 0 cm for site 2; section -30 cm for site 1, 3, and 5; section -60 cm for site 4). Therefore, each post was assigned to one of the following groups with different courses of remaining cross section along the post axis:

- Group 1: Remaining cross section increased from the bottom to the top of the post
- Group 2: Smallest remaining cross section between the ground line and 30 cm below
- Group 3: Remaining cross section decreased from the bottom to the top of the post

The percentage of posts assigned to these three groups can be seen in Table 4. In general, the percentage of posts belonging to group 1 increased with ascending age of the posts. On the other hand, the percentage of posts in group 2 decreased. Group 3 contained the smallest number of posts; at sites 4 and 5 none of the posts followed the criteria of this group. This assignment stands in contrast to the commonly accepted assumption, that the ground line is the most severe exposure for a wooden component in ground contact [De Groot et al. 1979, EN 252 (CEN 1990)], because here, supplies of atmospheric oxygen, soil water and nutrients are plentiful (Levy 1987). In this study only the younger posts (site 1 and 2) were decayed to the highest extent in this zone.

This finding became even more obvious when looking on the distribution of posts with respect to the section plane with the smallest remaining cross section (Fig. 3). The percentage of posts showing the smallest remaining cross section at the deepest part of the post increased with the posts' age. Thus, in most instances posts and poles may fail at the ground line, because at this point the bending moment is maximal, but it is not necessarily the zone of most severe decay.

3.2 Type and distribution of decay

White rot was the dominating decay type at all sites, in many cases in combination with soft rot: It was found on 95.2 % of the round posts and on 98.6 % of the splitted posts. In contrast, brown rot was detected at only two out of 354 section discs in total. This dominating role of white and soft rot on oak heartwood coincides with its poor performance in laboratory tests with white rot fungi and in terrestrial microcosms with soft rot as main decay type (Brischke et al. 2009).

Remarkable differences in the distribution and dissemination of decay were observed (Table 5 and Fig. 4). In most of the round posts decay started from the sapwood (95.2%), but also from radial cracks (33.3%). Only 4.2% of the posts showed interior rot starting from the heartwood.

1 The main starting points for decay in the splitted posts were radial cracks (98.1%), but in
2 58.1% of the posts not exclusively, but also from the heartwood.
3
4 The use of posts that include sapwood portions, which suffer from very low durability, is
5 supposed to be problematic as it may accelerate the infection of the post with wood-
6 destroying organisms. On the other hand, two contradictory assumptions can be made
7 concerning the role of sapwood for fungal infestation: 1. Heartwood will be infected faster, if
8 fungal mycelium is already established in the adjacent sapwood. 2. The sapwood ring acts as
9 a protective barrier, where decay fungi establish themselves, but do not or even very slowly
10 attack the heartwood portions, potentially because sap- and heartwood are susceptible to
11 different decay organisms. Although both hypotheses were not definitively approved, it
12 became evident, that remaining sapwood does not necessarily lead to a shortened service life
13 of the posts, as can be seen from the high percentage of splitted posts with decay starting from
14 the heartwood. As expected, on nearly all round posts decay started from the sapwood,
15 because it was surrounding these posts completely, and only a few showed interior heartwood
16 decay.
17
18 The role of deeper cracks acting as gates for water, fungal mycelium and spores into the wood
19 was often reported for preservative treated wood, where the treated shell frequently breaks up
20 through cracks (e.g., Helsing and Graham 1976, Morrell 1990), but may be transferred also to
21 untreated wood. However, quantitative studies on the meaning of cracks as starting points for
22 decay in untreated wood are rare and do rather indicate that their role is important (Clausen et
23 al. 2001, Augusta 2007).
24
25 Insect damage caused by *Phymatodes testaceus* L. was detected on 42.9% of the round posts
26 and on 43.2% of the splitted posts, but was mainly restricted to sapwood portions.
27
28
29
30
31
32
33
34
35
36
37

38 **3.3 Wood moisture content and soil parameters**

39 The wood moisture content of the posts generally decreased with increasing depth, whereby
40 only slight differences between the interior and exterior fifth of the posts were found (Table
41 6). Furthermore, the five sites were very similar in terms of the resulting wood moisture
42 content of the posts.
43
44 The moisture content of the soil varied between 7.7 and 29.5 % at the five sites. At sites 1, 4,
45 and 5 the soil moisture content decreased slightly with the soil depth, but was nearly constant
46 at sites 2 and 3 (Table 7). This finding coincided with the course of the water holding capacity
47 of the soils at the different sites: increasing with soil depth at sites 1, 4, and 5, and nearly
48 constant at sites 2 and 3. The pH values varied between 5.5 and 7.2 in deionised water and
49 between 4.8 and 6.3 in CaCl₂-solution. Although the soil moisture values represent only the
50
51
52
53
54
55
56
57
58
59
60

current status at the sites for one single day, it became obvious for all soil parameters that the differences between the sites were only marginal. The only exception was site 5 showing a high water holding capacity (46-61%), but low soil moisture contents (10-15%).

The complexity of the factors responsible for the intensity of decay at the posts became apparent from the coefficients of determination for potential correlations between the wood moisture content, the different soil parameters, and the remaining cross sections (Table 8). Neither the wood moisture content, nor the soil moisture content and the water holding capacity of the soil were correlated with the degree of decay of the posts ($R^2 < 0.8$). Furthermore, even the soil and the wood moisture content seemed to be independent from each other; the same for the water holding capacity and the corresponding moisture content of the soil. Finally, also no correlation arose between the age of the posts and the remaining cross sections (Fig. 5).

In contrast to in ground field tests, e.g., according to EN 252 (CEN 1990) it was not possible to assess the extent of decay in terms of strength or mass loss, because the posts in this study were very inhomogeneous in size and shape. Pursuant to the pick test according to EN 252 (CEN 1990), wood specimens are rated with respect to the depth and distribution of decay, which allows at least a calculative comparison with those results (Table 9). Augusta (2007) and Brischke et al. (2009) reported on numerous field tests with European oak heartwood in and above ground. Hereby a steady increase in the mean decay rating was observed till all specimens had failed, which stands in contrast to nearly identical mean remaining cross sections found in this study at sites 3, 4, and 5 after 20, 30, and 60 years in service. Secondly, decay started on oak heartwood immediately after its exposure in the ground without any time lag necessary for leaching of extractives or any other kind of detoxification in field tests (Brischke et al. 2009). This coincides with the unexpectedly early reduction of the posts' cross section at site 1 of this study after only 5 years in service (Table 2, Fig. 5).

The extremely long service life of many posts at site 4 and 5 seemed to stand in contrast with results of field tests according to EN 252 (CEN 1990), where the mean service life of oak specimens did not exceed 8 years (Brischke et al. 2009), but may be explained by the differences in size. There is still a controversial discussion about the influence of size and shape of a wooden component on its durability: While in above ground exposures bigger sized components seem to be compromised due to their lower capability to dry out after wetting (Sell 1980), opposite effects are discussed for timber in ground contact: Leicester et al. (2007) have shown that the impact of leaching of water soluble extracts or preservatives as well as the superficial degradation by bacteria is less pronounced for bigger components. As

1 in this study also remarkable decay was observed on posts after only 5 years in service, a
2 general rule for the impact of size or cross section of a component cannot be framed.
3
4

Formatted: Bullets and Numbering

5
6 **4 Conclusion**
7

8 The durability of oak and the service life of the posts, respectively, were affected by high
9 variation. Posts prematurely failing after only five years were found as well as posts still
10 serviceable after 60 years. Thus, a definite service life of oak posts to be expected in ground
11 contact was not indicated, and it seemed that the posts' service life is not simply correlated
12 with one of the soil parameters examined or the wood moisture content, respectively. On the
13 other hand, different peculiarities were observed and quantified: It was clearly shown that the
14 ground line, where moisture and oxygen conditions should be ideal for many fungi, was not at
15 all the most critical part of the posts; in fact it was 30 cm below the ground line. Furthermore
16 no significant negative impact of remaining sapwood portions on the durability of the
17 heartwood was found, but the important role of radial cracks for the initiation of decay
18 became apparent. In summary, it became obvious that case studies can seriously contribute to
19 a better understanding of decay processes and the reasons for wood durability. In regard to
20 this potential, important factors for the in-ground durability are size and shape of timber
21 components, which have not adequately been considered so far. For service life prediction of
22 timber components in general and for oak wood in particular further surveys seem to be
23 worthwhile and should include also above ground exposures. For calibration and adaption of
24 field and laboratory test methods valuable hints can be expected when aiming at a
25 methodology as close to reality as possible.
26
27
28
29
30
31
32
33
34

Formatted: Bullets and Numbering

35
36 **5 References**
37

38 Acker Van J, Stevens M, Carey J, Sierra-Alvarez R, Militz H, Le Bayon I, Kleist G, Peek R-D
39 (2003) Biological durability of wood in relation to end-use. Part 1. Towards a
40 European standard for laboratory testing of the biological durability of wood. Holz
41 Roh- Werkst 61:35-45
42
43 Aloui F, Ayadi N, Charrier F, Charrier B (2004) Durability of European oak (*Quercus*
44 *petraea* and *Quercus robur*) against white rot fungi (*Coriolus versicolor*): relations
45 with phenol extractives. Holz Roh- Werkst 62:286-290
46
47 Augusta U (2007) Untersuchung der natürlichen Dauerhaftigkeit wirtschaftlich bedeutender
48 Holzarten bei verschiedener Beanspruchung im Außenbereich. Dissertation,
49 University of Hamburg
50
51
52
53
54
55
56
57
58
59
60

- Ayadi N, Charrier B, Irmouli M, Charpentier JP, Jay Allemand C, Feuillat F, Keller R (2001) Interspecific variability of European oak durability against white rot fungi (*Coriolus versicolor*): Comparison between sessile oak and peduncle oak (*Quercus petraea* and *Quercus robur*). Document No. IRG/WP 01-10393. International Research Group On Wood Protection, Stockholm, Sweden
- Brischke C, Welzbacher CR, Rapp AO, Augusta U, Brandt K (2009) Comparative studies on the in-ground and above-ground durability of European oak heartwood (*Quercus petraea* Liebl. and *Quercus robur* L.). Eur J Wood Prod. Online first. DOI 10.1007/s00107-009-0329-x
- CEN (1990) EN 252 Wood preservatives - Field test method for determining the relative protective effectiveness of a wood preservative in ground contact. CEN (European committee for standardization), Brussels
- CEN (1994) EN 350-2 Durability of wood and wood-based products - Natural durability of solid wood - Part 2: Guide to natural durability and treatability of selected wood species of importance in Europe. CEN (European committee for standardization), Brussels
- CEN (2005) CEN/TS 15083-2 Durability of wood and wood-based products - Determination of the natural durability of solid wood against wood-destroying fungi, test methods - Part 2: Soft rotting micro-fungi. CEN (European committee for standardization), Brussels
- Clausen CA, Ross RJ, Forsman JW, Balachowski JD (2001) Condition assessment of roof trusses of Quincy Mine Blacksmith shop in Keweenaw National Historical Park. Research note FPL-RN-0281, United States Department of Agriculture, Forest Products Laboratory.
- De Groot RC, Feist WC, Eslyn WE, Gjovik LR (1979) Protecting wood fences for yard and garden. Publication Serial No. A 3052, Cooperative Extension Programs, University of Wisconsin, USA
- DIN (1977) DIN 52183 Prüfung von Holz. Bestimmung des Feuchtigkeitsgehaltes. Deutsches Institut für Normung, Berlin
- Guilley E, Charpentier JP, Ayadi N, Snackers G, Nepveu G, Charrier B (2004) Decay resistance against *Coriolus versicolor* in Sessile oak (*Quercus petraea* Liebl.): analysis of the between-tree variability and correlations with extractives, tree growth and other basic wood properties. Wood Sci Technol 38:539-554
- Haneca K, Van Acker J, Beeckman H (2005) Growth trends reveal the forest structure during Roman and Medieval times in Western Europe: a comparison between archaeological

- and actual oak ring series (*Quercus robur* and *Quercus petraea*). Ann For Sci 62:797-805
- Helsing GG, Graham RD (1976) Saw kerfs reduce checking and prevent internal decay in pressure-treated Douglas-fir poles. Holzforschung 30: 184-186.
- Humar M, Fabčič B, Zupančič M, Pohleven F, Oven P (2008) Influence of xylem growth ring width and wood density on durability of oak heartwood. Int BioBio. Online first. DOI:10.1016/j.ibiod.2008.03.010.
- ISO (2005) ISO 10390 Soil quality - Determination of pH. International Organization for Standardization, Geneva
- ISO (2000) ISO 11268-2 Soil quality - Effects of pollutants on earthworms (*Eisenia Fetida*) - Part 2: Determination of effects on reproduction. International Organization for Standardization, Geneva
- Kollert W (1991) Die Eiche im Holzaufkommen und Außenhandel. Forstwiss. Cent.bl. 110: 196-206.
- Leicester RH, Wang C-H, Nguyen MN, Foliente GC (2005) Engineering models for biological attack of timber. TT4-217. Proceedings of the 10th Conference on Durability of Building Materials and Components, Lyon, France
- Levy JF (1987) The natural history of the degradation of wood. Phil. Trans. R. Soc. Lond. A 321: 423-433.
- Morrell JJ (1990) Effect of kerfing on performance of Douglas-fir utility poles in the Pacific Northwest. Document No. IRG/WP/3604. International Research Group On Wood Protection, Stockholm, Sweden
- Schepers J (1994) Haus und Hof westfälischer Bauern. Aschendorffsche Verlagsbuchhandlung, Münster.
- Sell J (1980) Oberflächenbehandlung von Brettschichtholzträgern: Anforderungen: Anforderungen, praktische Erfahrungen und Versuchsergebnisse. Holz-Zent.bl. 106: 629-630.

Table 1. Geographic characterization of the sites, corresponding number of posts existent, and number, dimension, and type of posts examined (Standard deviation in brackets).

Tabelle 1. Geografische Charakterisierung der Standorte, zugehörige Anzahl vorhandener Pfähle, Anzahl, Abmessungen und Typ der untersuchten Pfähle (Standardabweichung in Klammern).

	Site 1	Site 2	Site 3	Site 4	Site 5
Previous service life [a]	5	10	20	30	60+x ¹
Location	Versmold-Bockhorst	Versmold-Bockhorst	Versmold-Bockhorst	Werther-Rotingdorf	Werther-Rotingdorf
Latitude	52°4'29''	52°5'6''	52°4'29''	52°5'6''	52°5'6''
Longitude	8°12'2''	8°12'2''	8°12'2''	8°25'16''	8°25'16''
Altitude [m]	70	70	70	130	130
Posts existent	44	67	18	66	25
Posts examined					
Round posts	0	1	10	7	3
Splitted posts	2	9	2	18	3
Double splitted posts	13	10	3	5	9
Total	15	20	15	30	15
Mean length [cm]	189 (4)	190 (9)	195 (5)	174 (16)	168 (16)
Mean length in ground [cm]	70 (6)	86 (6)	71 (4)	71 (16)	49 (16)
Original heartwood cross section [cm ²]	130 (34)	134 (34)	168 (45)	104 (25)	85 (28)

¹the posts have been in service for at least 60 years.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

Table 2. Mean remaining cross section of the posts for the different sites and section planes.

Tabelle 2. Mittlerer Restquerschnitt der Pfähle für die unterschiedlichen Standorte und Schnittebenen.

Site	Previous service life [a]	Mean remaining cross section [%]				
		+30 cm	0 cm	-30 cm	-60 cm	Minimum ²
1	5	95.2	90.0	86.9	90.2	84.9
2	10	87.2	78.5	79.1	83.9	71.8
3	20	74.4	53.5	39.3	45.7	34.9
4	30	91.2	74.9	56.1	48.4	42.9
5	60+x ¹	90.6	73.5	40.9	77.5	40.9

¹ the posts have been in service for at least 60 years.

² refers to the section plane with the least remaining cross section of each post

Table 3. Percentage of posts in classes of remaining cross section for the different sites.**Tabelle 3. Anteil von Pfählen in Klassen des verbliebenen Restquerschnitts für die unterschiedlichen Standorte.**

Site	Previous service life [a]	Percentage of posts with remaining cross section x [%]			
		100 % > x ≥ 90 %	90 % > x ≥ 75 %	75 % > x ≥ 50 %	x < 50 %
1	5	60.0	26.7	6.7	6.7
2	10	5.0	45.0	40.0	10.0
3	20	0.0	0.0	26.7	73.3
4	30	0.0	10.0	50.0	40.0
5	60+x ¹	0.0	6.7	46.7	46.7

¹ the posts have been in service for at least 60 years.

Table 4. Percentage of posts in groups with different courses of remaining cross section along the post axis for the different sites. Group 1: Remaining cross section increased from the bottom to the top of the post. Group 2: Smallest remaining cross section between the ground line and 30 cm below. Group 3: Remaining cross section decreased from the bottom to the top of the post.

Tabelle 4. Anteil von Pfählen in Gruppen unterschiedlichen Verlaufs des verbliebenen Restquerschnitts entlang der Pfahlachse für die unterschiedlichen Standorte. Gruppe 1: Restquerschnitt steigt mit der Pfahlhöhe an. Gruppe 2: Geringster Restquerschnitt zwischen der Boden-Luft-Zone und 30 cm darunter. Gruppe 3: Restquerschnitt sinkt mit der Pfahlhöhe.

Site	Previous service life [a]	Percentage of posts [%]		
		Group 1	Group 2	Group 3
1	5	20	60	20
2	10	20	65	15
3	20	60	33	7
4	30	67	33	0
5	60+x ^{1, 2}	87	13	0
All		51	41	8

¹ the posts have been in service for at least 60 years.
² the depth of burying of the posts in group 1 at site 5 was less than 60 cm.

Table 5. Types of distribution and dissemination of decay in the posts.**Tabelle 5. Verteilungs- und Ausbreitungsformen der Fäulnis in den Pfählen.**

Type of decay distribution	Percentage of posts [%] ¹	
	Round posts	Splitted posts
Starting from sapwood	95.2	13.5
Starting from heartwood	4.8	58.1
Starting from radial cracks	33.3	98.1

¹A post was assigned to one of the groups if at least half of the section discs fulfilled the criteria

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

Table 6. Mean wood moisture content of the interior and exterior fifth of the posts in different section planes for the different sites.

Tabelle 6. Mittlere Holzfeuchte im inneren und äußeren Fünftel der Pfähle in den jeweiligen Schnittebenen an den unterschiedlichen Standorten.

Site	Previous service life [a]	Mean wood moisture content [%]							
		Interior fifth of the post				Exterior fifth of the post			
		+30 cm	0 cm	-30 cm	-60 cm	+30 cm	0 cm	-30 cm	-60 cm
1	5	21	47	65	83	20	50	92	102
2	10	20	53	73	84	17	54	88	101
3	20	19	34	85	93	17	30	103	118
4	30	18	42	86	110	17	56	107	129
5	60+x ¹	17	47	97	100	17	42	96	107

¹the posts have been in service for at least 60 years.

Table 7. Mean moisture content, water holding capacity, and pH of soil surrounding the posts in different section planes and for the different sites.

Tabelle 7. Mittlere Feuchte, Wasserhaltekapazität und pH-Wert des Bodens in unmittelbarer Nähe der untersuchten Pfähle in den jeweiligen Schnittebenen an den unterschiedlichen Standorten.

Site	Previous service life [a]	Mean soil moisture content [%]			Water holding capacity [%]			pH in deionised water	pH in 0.01 m CaCl ₂
		0 cm	-30 cm	-60 cm	0 cm	-30 cm	-60 cm	all	all
1	5	22	19	19	50	44	35	7.2	6.3
2	10	14	15	16	44	42	40	5.5	4.8
3	20	20	22	22	50	50	50	5.9	5.2
4	30	28	27	21	49	46	39	6.1	5.5
5	60+x ¹	15	12	10	61	54	46	5.8	5.3

¹the posts have been in service for at least 60 years.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

Table 8. Interrelationship between the different investigation parameters, expressed as coefficient of determination R^2 for linear smoothing functions, at the different sites.

Tabelle 8. Zusammenhang zwischen den verschiedenen Untersuchungsparametern ausgedrückt als Bestimmtheitsmaß R ² einer linearen Ausgleichsfunktion für die unterschiedlichen Standorte.							
Site	Previous service life [a]	Coefficient of determination R ²					
		Variable 1					
		Remaining cross section [%]	Remaining cross section [%]	Remaining cross section [%]	Soil moisture content [%]	Water holding capacity [%]	Water holding capacity [%]
		Variable 2					
		Wood moisture content ² [%]	Soil moisture content [%]	Water holding capacity [%]	Wood moisture content ² [%]	Wood moisture content ² [%]	Soil moisture content [%]
1	5	0.0031	0.0093	0.0008	0.0241	0.7161	0.0728
2	10	0.0006	0.1164	0.0359	0.2334	0.0078	0.2478
3	20	0.0783	0.5686	0.3443	0.0792	0.0033	0.1497
4	30	0.5802	0.3546	0.3481	0.6151	0.6927	0.8032
5	60+x ¹	0.1008	0.0057	0.0027	0.4509	0.5494	0.6688

¹the posts have been in service for at least 60 years.
²Wood moisture content measured in the interior fifth of the posts.

Table 9. Decay rating for in-ground field tests according to EN 252 (CEN 1990) and corresponding remaining cross sections of specimens.

Tabelle 9. Abbaubewertung für Eingrabeversuche nach EN 252 (CEN 1990) und entsprechende Restquerschnitte der Prüfkörper.

Decay rating after EN 252 (CEN 1990)	Description	Remaining cross section of specimen x [%]
0	No attack	$x = 100$
1	Slight attack	$100 > x \geq 88$
2	Moderate attack	$88 > x \geq 67$
3	Severe attack	$67 > x \geq 48$
4	failure	$48 > x$

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

Fig. 1. Cutting schedule of fence posts for determination of remaining cross sections and wood moisture content (all dimensions in mm).

Abb. 1. Schnittplan zur Entnahme von Pfahlscheiben für die Bestimmung von Restquerschnitt und Holzfeuchte (alle Angaben in mm).

Fig. 2. Determination of remaining cross section. Grey line: Reconstructed original heartwood cross section. Black line: Remaining undecayed heartwood cross section.

Abb. 2. Bestimmung des verbliebenen Restquerschnitts. Graue Linie: Rekonstruierter ursprünglich vorhandener Kernholzquerschnitt. Schwarze Linie: Querschnitt des verbliebenen, nicht verfauten Kernholzes.

Fig. 3. Percentage of posts with the smallest remaining cross section in different section planes for the different sites.

Abb. 3. Anteil von Pfählen mit dem geringsten verbliebenen Restquerschnitt in den jeweiligen Schnittebenen an den unterschiedlichen Standorten.

Fig. 4. Examples for different types of distribution and dissemination of decay in round posts. Left: Decay starting from the sapwood. Centre: Decay starting from the central heartwood. Right: Decay starting mainly from radial cracks.

Abb. 4. Beispiele für die Verteilung und Ausbreitung von Fäulnis in Rundpfählen. Links: Fäulnis vom Splintholz ausgehend. Mitte: Fäulnis vom inneren Kernholz ausgehend. Rechts: Fäulnis überwiegend von radialen Rissen ausgehend.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

Fig. 5. Interrelationship between remaining cross section and the previous service life of the posts (refers to the section plane with the least remaining cross section of each post).

Abb. 5. Zusammenhang zwischen Restquerschnitt und bisheriger Gebrauchsdauer der Pfähle (berücksichtigt wurde jeweils der minimale Restquerschnitt des Pfahls).