Experimental response and vibrational characteristics of a slotted rotor

Jean-Jacques Sinou

► To cite this version:

Jean-Jacques Sinou. Experimental response and vibrational characteristics of a slotted rotor. Communications in Nonlinear Science and Numerical Simulation, 2009, 14, pp.3179-3194. 10.1016/j.cnsns.2008.10.024 . hal-00361665

HAL Id: hal-00361665

<https://hal.science/hal-00361665>

Submitted on 8 Feb 2013

HAL is a multi-disciplinary open access archive for the deposit and dissemination of scientific research documents, whether they are published or not. The documents may come from teaching and research institutions in France or abroad, or from public or private research centers.

L'archive ouverte pluridisciplinaire **HAL**, est destinée au dépôt et à la diffusion de documents scientifiques de niveau recherche, publiés ou non, émanant des établissements d'enseignement et de recherche français ou étrangers, des laboratoires publics ou privés.

Experimental response and vibrational characteristics of a slotted rotor

J-J. Sinou

Laboratoire de Tribologie et Dynamique des Systèmes UMR CNRS 5513
Ecole Centrale de Lyon, 36 avenue Guy de Collongue, 69134 Ecully Cedex, France.
jean-jacques.sinou@ec-lyon.fr

Abstract

This paper proposes to perform experimental tests on the vibrational characteristics of a slotted rotor. Changes in the responses of the $n \times$ amplitudes are examined for small and deep slots that can be considered as open cracks. The evolutions of the orbital patterns and the $2 \times$ harmonic components near one-half of the first critical speed are investigated in details to propose an efficient indicator of the presence of slots in rotor: a special attention is given to both the comparison of the horizontal and vertical maximum amplitudes of the $2 \times$ harmonic components, and changes in the size of the inside loop of orbits when the rotor is passing through one-half of the first critical speed.

A huge experimental work considering the influences of the slot depth and the orientation of unbalance relative to the slot direction is investigated in order to examine the possibility of detecting the presence of a transverse slot in rotors.

1 Introduction

Dynamic behavior of cracked rotors has been a subject of substantial interest for the last three decades. Reviews on cracked rotors and structures can be found in [1–3]. Most of the previous studies focused on detecting cracks in rotor by means of the observation of the lateral non-linear rotor's steady-state vibrations using only numerically analysis [4–7]. They indicated that the presence of a crack induces changes in the $2 \times$ and $3 \times$ harmonic components of steady-state response of the rotor system. They also proposed to exploit the evolutions of orbital pattern of the cracked rotor at one-half of the first critical speed for the non-destructive detection of cracks in rotors.

More recently, several researchers have studied the dynamic response of cracked rotors combining theoretical and experimental approaches. Generally, experimental tests are undertaken in order to illustrate the efficiency of the proposed methodologies and on-line diagnostic techniques. For example, Seibold and Weiner [8] proposed a time domain identification algorithm based on the Extended Kalman Filter for the localization of cracks in rotating machinery. Experimental and numerical investigations on the response of the cracked rotor to periodic axial excitation were carried out by Darpe [9] to prove that coupling of bending and longitudinal vibrations may be used as the signature of a transverse crack in rotors. Bachschmid et al. [10–12] proposed a model-based diagnostic approach with a least-squares identification for the detection

of cracks in rotors. The reliability of the proposed methodology was validated by experimental tests on industrial rotating machineries with an excellent accuracy obtained in identifying both the position and depth of cracks [12].

Finally, relatively less work is reported on a complete experimental study of the steady-state non-linear vibrations of a rotor with various crack depths. Exception are the works of Pennacchi et al. [12], Darpe et al. [13], Adewusi and Al-Bedoor [14] and Mayes and Davies [15, 16]. These works have been widely used by other researchers to validate their theoretical studies. These experimental studies showed that the steady-state vibration signal of a propagating crack produces changes in $1\times$ and $2\times$ amplitudes and induces the classical two-loops orbit at one-half of the critical speed. Moreover, Adewusi and Al-Bedoor [14] noted that the $3\times$ amplitudes appear just before the rotor's fracture. In these papers, the authors proposed to generate a real propagating transverse crack in the rotor.

In the following study, the type of crack that has been chosen is a slot (i.e. the crack always remains open). As indicated by Sabnavis et al. [3], cracks that are assumed to be open all the time are also known as gaping cracks or called "notches". Even if this slot does not reproduce exactly the typical propagating and breathing behavior of a crack in rotors, it allows to show the effects of an always open crack due to the rotor stiffness unsymmetry introduced by the slot. For the following study, this type of crack reproduction has been chosen for two main reasons. Firstly the reproduction of a real propagating crack in a rotor is a very difficult and expensive work especially if a huge experimental work is required. As explained by Sabnavis et al. [3], most experimental work is focused on open cracks due to the fact that a slot is easy to mimic in a laboratory environment. Secondly, a transverse breathing crack is experimentally done by starting from a slot that allows to initiate a fatigue crack at the desired location. Then, the repeated experiment of cyclic loading cause the crack propagation as a consequence of fatigue solicitation [12, 14]. For example, Mayes and Davies [15] decided to rotate the shaft slowly with a static load applied to the crack location. Darpe [13] proposed to place the rotor in a three-point-fatigue bending machine and to subject the shaft to cyclic loading. The disadvantage of this procedure is that the crack is firstly done in the shaft and then the complete rotor system is assembled. As explained by Pennacchi et al. [12], this fact implies that it can be difficult to have a valid reference case of the healthy rotor: differences in alignment and unbalance can be introduced and so comparisons with the healthy rotor can be difficult. As explained by some researchers [12, 15], the shaft is broken at the end of tests in order to reveal the fracture surface of the crack. Moreover, the initial slot and the propagating crack are both present in the shaft and so they influence the vibrational characteristic of the cracked rotor. Then, the shaft characteristics can be changed due to the cyclic loading used to create the crack and the appearance of a bow in rotor can be introduced. Thus comparisons of the vibration characteristics of the healthy rotor with those of the rotor with different cracks can be difficult to be done precisely. It can be noted that Mayes and Davies concluded in their study [15] that a horizontal cracked shaft, except for large crack where the depth is greater than the radius of the shaft, behaves as a slotted shaft with additional excitation due the crack breathing. They also indicated that their experimental results for a cracked rotor can be compared with the results obtained for an asymmetric shaft (based on the results of the experimental study of Taylor [17]). Numerical comparisons of the response of cracked and asymmetric rotors were also proposed by Henry and Okah-Avae

[18]: responses at the main critical speed and at one-half of the critical speed and the effect of eccentricity for both a linear asymmetry and a crack were studied. The authors indicated that the crack can tend to remain always open in the vicinity of the main critical speed due to the combined effect of eccentricity orientation and gravity. So, the shaft can behave like an asymmetric shaft if the eccentricity keeps the crack open. On the other hand, they also observed that the shaft behaves like a symmetric shaft if the eccentricity orientation is such to close the crack. The opening/closing phenomenon was also investigated by Jun et al. [19]. They performed an extensive numerical study of the necessary condition for a crack to remain always open or close, or to breathe. They indicated that opening and closing conditions are dependent upon the crack depth and unbalance. For example, they observed that the crack tends to breathe or to remain always open before the first critical speed if the unbalance and the crack are in the same direction. Above the first critical speed, the crack tends to remain always close. The opening/closing phenomenon is reversed if the unbalance coincides with the opposite direction of the crack. The authors indicated that the rotor tends to breathe when the direction of the unbalance is perpendicular to that of the crack (except near the critical speed). They also suggested that the crack tends to alternate the open and closed states when the unbalance becomes small. When the unbalance is relatively large, the crack tends to remain open or closed. Plaut et al. [20] also studied behavior of a cracked rotating shaft. They compared the responses of a shaft with a breathing crack to those for a crack that remains open and to those for an uncracked shaft. They demonstrated that the angle between the crack and the unbalance can induce significant changes in the responses of the rotor.

Finally, as suggested by Bachschmid et al. [21], different thermal states can force the crack to be always open. For example, Bachschmid et al. [21] explained that the thermal stresses tend to prevent and to reduce the breathing behavior for a heating transient (a positive temperature gradient). Moreover, if a cooling transient is observed (a negative temperature gradient), the crack can be always open. So the thermal states can drastically affect the breathing behavior.

So the limits of the experimental results that will be proposed in this paper concern the case of a slotted rotor, the vibrational behavior of a slotted rotor being sufficient to give the primary effects of the vibration changes for a rotor with an open crack. A complete study of the effect of different open crack depths, a complete comparison with the healthy rotor by considering the evolutions of the n^{th} orders (with $n = 1, 2, \dots, 6$) and the orbits (at the first critical speed and at the $\frac{1}{n}$ sub-critical resonant speeds) will be studied. The objective of this present study is to perform an huge experimental analysis of the effects of an open crack on the dynamic characteristics of rotors. Not only the evolutions of the n^{th} orders (for $n = 1, \dots, 6$) as a function of the rotating speed and the crack depths, but also interaction between the front open crack and the unbalance, and orbital evolutions will be discussed.

This paper is divided into three parts. Firstly, the experimental setup is presented. Then, the evolutions of the $n \times$ amplitudes and orbital evolution in the horizontal and vertical directions are investigated for the healthy and slotted rotors. Finally, the influence of the open crack depth and the interactions between the open crack and the unbalance parameters (intensity and orientation with the front crack) are undertaken.

2 Experimental setup

The equipment used for the experiment tests is composed of a Rotor Kit with a motor speed control and data acquisition interface unit that is controlled by the I-DEAS Software. The measured vibratory data are transmitted to a PC via the National Instruments PCI-4472 channel dynamic signal acquisition devices. Then the data are transferred from I-DEAS Software to Matlab in order to be examined and manipulated to obtain the $n \times$ amplitudes and the orbital pattern.

The picture of the experimental rig is shown in Figure 1. This test rig that consists of a steel shaft of $480mm$ long and $10mm$ diameter, is simply supported at both ends by two bush bearings. The experimental system is directly mounted on a rigid massive concrete table isolated from the environment. The left end of the rotor is coupled with an electric motor by means of a flexible coupling. The shaft carries one disc made of steel and placed at $382mm$ from the left end of the shaft. Disc dimensions are $75mm$ diameter and $35mm$ thickness. The disc has sixteen holes that are separated by regular degree angle in order to be able to investigate the influence of the unbalance and angle between the front crack and imbalance intensity. Before the experimental tests, the level of the residual unbalance of the healthy rotor has been estimated at $0.18gm$ and $168deg$.

The location of the open crack is at $243mm$ from left end of the rotor. The rotor's cracks are made by cutting a piece of width $0.2mm$ with a jeweler's saw. Runs are done at five different crack depths (from the small crack $\mu = 0.2$ to depth equals to the half of the shaft diameter $\mu = 1$, with intervals of non-dimensional crack depth $\delta\mu = 0.2$) and with the uncracked rotor. μ defines the non-dimensional crack depth and is given by $\mu = \frac{h}{R}$ where R is the radius of the shaft and h the depth of the crack. Each cutting is realized on the complete rotor without dismantling operations in order to be able to compare all the experimental tests with various crack depths. The cut introduces an open crack in the rotor. Indeed the lateral deflections being small, the slot may not completely close and would not eventually breathe. So the rotor under study may be considered as a slotted rotor (i.e. a rotor with an open crack) due to the cut which in turn may give different dynamic response from a rotor having a breathing crack. However, this experimental procedure has been chosen to be sure that changes in the n^{th} orders, the non-linear responses and the orbits are only due to the evolutions of the slot depth and not to structural modifications that may be introduced by dismantling operations.

To assess the non-linear dynamic of the cracked rotor and to investigate the effects of the presence of a transverse crack, the displacements of the shaft are measured in several transversal planes. Six non-contact displacement transducers that are mounted in both the horizontal and vertical directions are used in order to measure the displacement of the rotor. They consist of two orthogonal proximity probes for each plane and are placed at $70mm$ (plane A1), $210mm$ (plane A2) and $440mm$ (plane A3) from the left end of the shaft. The position of the three planes are given in Figure 1. Therefore, a tacho signal is used to measure the rotor speed that is measured and monitored at regular intervals during the tests. A variability of $2.5rpm/s$ for the rotor is chosen during run-ups and the operational range is from 0 to $4000rpm$.

Figure 1: Picture of the experimental rig and the transverse crack

3 Experimental results

The experimental procedure is divided into three parts. The first set of experiments are done for the healthy shaft. Secondly the evolutions of the non-linear behavior and the $n \times$ associated amplitudes of the slotted rotor are investigated by increasing the speed of the rotor (with a constant acceleration speed profile) until the first critical speed is reached. The effects due to the interactions between the open crack and the imbalance parameters (intensity and orientation with the front crack) are undertaken. Finally, the orbital evolutions are studied for various crack depths when the rotor passes through one-half and one-third of the first critical speed.

3.1 Healthy rotor

First of all, two cases are considered for the healthy rotor. The first case concerns the initial residual unbalance that has been estimated at $0.18gm$ and $168deg$. The second case corresponds to the addition of an unbalance of $1gm$ at $0deg$.

An order tracking test (DSP method of filtering the measured time history signal) is performed to access the harmonic contents of the non-linear vibrations of the healthy rotor when the rotor runs from 0 to $4000rpm$. Results of the $n \times$ amplitudes ($n = 1, 2$ and 3) and phases in plane A2 are presented in Figures 2 and 3 for the unbalance of $0.18gm$ at $168deg$, and $1gm$ at $0deg$., respectively.

Some of the order tracking plots (the whole signal magnitude called the composite power, orders 1, 2 and 3) are presented in Figures 4 at the locations A1 and A3 in both the horizontal and vertical directions for the second unbalance case (i.e. $1gm$ at $0deg$.).

The order 1 response peaks (Figures 2(a) and the blue lines in Figures 4) correspond to the first critical speeds of the healthy rotor. These figures show that the first rotor critical speed is around $2500rpm$.

From the phase evolution of the vertical and horizontal plots in Figure 2(a), the precession of the rotor is forward below $2700rpm$ and above $2800rpm$: the vertical vibration leads the horizontal vibration. Between $2700rpm$ and $2800rpm$, the rotor vibrates in reverse in the period between the two principal resonances (i.e. the precession is reverse) and the horizontal vibration leads the vertical vibration. The simplest and predominant reason for this reverse orbiting is the asymmetric (i.e. anisotropic) support stiffness of the rotor system, as showing in the picture of the rotor system (see Figure 1). This is typically the case of most horizontal machines that are weaker horizontally.

From the $2\times$ harmonic components in Figures 2(c), 3(c) and Figures 4, it can be inferred the $2\times$ harmonic components are present. From the analysis of the $2\times$ amplitudes in Figures 4, the $2\times$ harmonic components are about $10 - 15\mu m$ for planes A1 and A3, and $25\mu m$ for plane A2) at the $\frac{1}{2}$ sub-critical resonances. The $3\times$ harmonic components appear to be very small for the three planes in both the vertical and horizontal directions (with small peaks about $1\mu m$ for planes A1 and A3, and $1.5\mu m$ for planes A2 when the rotor is passing through $\frac{1}{3}$ of the first critical speed). The presence of the $2\times$ component are typically due to the combination of the asymmetry and a steady-state radial load that is generally due to the gravity on horizontal rotor.

Then Figures 5 show the orbital evolutions of the healthy rotor at the middle of the shaft (plane A2) around one-half of the first critical speed, wherein a small distorted two-loop orbit is formed.

To clarify the presence of other orders than $1\times$, Figure 6 illustrates the evolutions of the $n\times$ amplitudes (for $n = 0.25 - 6.25$ with a step of 0.25). To compare the magnitudes of each order, the $n\times$ amplitudes are normalized on the speed range under study as follows:

$$X_{normalized} = \frac{\log(X) - \log(X_{min})}{\log(X_{max}) - \log(X_{min})} \quad (1)$$

where X_{min} and X_{max} define the minimum and maximum amplitudes of all the $n\times$ amplitudes on the speed range. Figure 6 shows that not only the second and third orders are present at the $\frac{1}{2}$ and $\frac{1}{3}$ sub-critical resonant speeds, respectively, but also the fourth, fifth and sixth orders at the $\frac{1}{4}$, $\frac{1}{5}$ and $\frac{1}{6}$ sub-critical resonant speeds, respectively. However, the $2\times$, $3\times$, $4\times$, $5\times$, $6\times$ amplitudes are small in comparison with the vibration amplitudes of first order. Finally, it can be also observed that the n^{th} orders (with $n = 1, 2, \dots, 6$) are present when the rotor speed reaches the first critical speed, even if the associated amplitudes are not very significant in comparison with the first order of the non-linear response of the healthy rotor.

The small amount . that are mechanisms generating . components when the system behavior is non-linear. In fact, the presence of the bushings causes a non-linear response of the rig: super-harmonics are excited by synchronous excitations (like the residual or the additional unbalance) even without the presence of the slot. Thus the test-rig response is non-linear by itself and the effect of the slot is the combination of two non-linear responses. The non-linear response of the slot cannot be evaluated as simply additional to that of the rotor without the slot.

The small amount of super-harmonic components other than $1\times$ can be attributed to the bow-related side load on the shaft-disk, and the rotor anisotropy and the unbalance that are mechanisms generating $2\times$ and $3\times$ harmonic frequency components when the system behavior is non-linear. In fact, the presence of the bushings causes a non-linear response of the rig: super-harmonics are excited by synchronous excitations (like the residual or the additional unbalance) even without the presence of the slot. Thus the test-rig response is non-linear by itself and the effect of the slot that will be studied in the following section of the paper is the combination of two non-linear responses. The non-linear response of the slot cannot be evaluated as simply additional to that of the rotor without the slot.

3.2 Slotted rotor

3.2.1 $n\times$ amplitudes

The effects of an open crack on the response curves of the rotor system are first considered in the present section. Figures 2 and 3 indicate changes of the $1\times$, $2\times$ and $3\times$ amplitudes and phases for the healthy and slotted rotor in plane A2 (two unbalance configurations are given: the first case concerns the initial residual unbalance of $0.18gm$ at $168deg$. and the second corresponds to an added unbalance of $1gm$ at $0deg$). Then, Figures 4 show the evolutions of the non-linear responses and the $1\times$, $2\times$ and $3\times$ amplitudes for both the healthy and slotted rotor at the locations A1 and A3 for the second unbalance case ($1gm$ at $0deg$). In the case of the open cracked rotor, the crack is situated at the middle of the shaft (as shown in Figure 1) and the non-dimensional crack depth is equal to 1, which corresponds to the case of half the area of the cross-section is missing due to the open crack.

In regards to the $1\times$ amplitudes, an offset at very low rotating speeds is observed (see Figure 3(b) or Figures 4 (a) and (b) for example). This fact indicates a significant and permanent bow in the rotor. Then, the change in $1\times$ amplitudes at the first critical speed is clearly observed in all cases. From the analysis of the results for the initial residual unbalance ($0.18gm$ at $168deg$) in Figures 2(a) and (b) for the plane A2, the vertical and horizontal synchronous amplitudes varies from $75\mu m$ and $48\mu m$ to $210\mu m$ and $220\mu m$, respectively. With an added unbalance of $1gm$ at $0deg$, the horizontal and vertical $1\times$ amplitudes change from $440\mu m$ and $250\mu m$ to $200\mu m$ and $180\mu m$, respectively. Typically these changes in synchronous amplitudes are caused by the shaft bowing due to the asymmetric transverse open crack. The bow is introduced by the slot and so the effect of the slot is equivalent of an additional unbalance. In our case, it can be observed that the offset due to this bow is important. For the slotted rotor, the bow generate around $10\mu m$ and $15\mu m$ in the horizontal direction for the planes A1 and A2 (see Figures 4(a) and (c) or Figure 3(b)).

Then, Figures 2, 3(c), and 4 illustrate the fact that the $2\times$ and $3\times$ harmonic amplitudes for the slotted rotor are more significant than that of the healthy rotor when the rotor reaches one-half and one-third of the first critical speed, respectively.

The high amplitudes of the peaks (about $30 - 40\mu m$ for planes A1 and A3, and $55 - 75\mu m$ for plane A2) at one-half of the first critical speed are clearly due to the open crack. Moreover, the resonance amplitudes of the $3\times$ components (about $3 - 5\mu m$ for planes A1 and A3, and $5 - 8\mu m$

for plane A2) at one-third of the first critical speed, are recognisable. Even if the $3\times$ amplitudes are not very important, they are three times more important than for the healthy rotor and so clearly show the effect of the open crack.

The same conclusions can be done from the analysis of the $2\times$ and $3\times$ amplitudes in Figures 2. The peaks of the horizontal and vertical $2\times$ amplitudes change from $25\mu m$ and $24\mu m$ to $52\mu m$ and $75\mu m$ at one-half of the first critical speed, respectively. At one-third of the first critical speed, the $3\times$ amplitudes changes from $1\mu m$ to $6\mu m$ in both the vertical and horizontal directions. Then, the rotating speeds where the $2\times$ and $3\times$ maximum amplitudes are observed (at one-half and one-third of the first critical speed, respectively) decrease significantly (from $1465rpm$ to $1410rpm$ for the $\frac{1}{2}$ sub-critical resonant speeds, and from $980rpm$ to $960rpm$ for the $\frac{1}{3}$ sub-critical resonant speeds from the analysis of the $2\times$ amplitudes in Figures 4). Moreover, the $3\times$ amplitudes increase at $\frac{1}{2}$ sub-critical resonant speed and at the first critical speed due to the presence of the open crack.

Then, it clearly appears that the $2\times$ and $3\times$ harmonic components are present when the rotor is passing through nearly the first critical speed.

From the analysis of the $2\times$ and $3\times$ amplitudes in Figures 4, it appears that the $2\times$ and $3\times$ amplitudes are multiplied by three due to the presence of the open crack. So the differences of $2\times$ and $3\times$ harmonic components between the healthy and slotted rotors are significant enough in order to be used as a diagnostic tool.

Finally, the $n\times$ normalized amplitudes are shown in Figure 7. Not only the $2\times$ and $3\times$ amplitudes are present, but also the $4\times$, $5\times$ and $6\times$ harmonic components are visible at $\frac{1}{2}$ sub-critical resonant speed whereas they are not visible for the healthy rotor. Moreover, it clearly appears that the $2\times$, $3\times$ and $4\times$ normalized amplitudes are more significant when the slotted rotor reaches one-half, one-third and one-fourth of the first critical speed, respectively.

In regards to the $2\times$ amplitudes in Figures 6 and 7, it is observed that the speed range where $2\times$ amplitudes are recognisable increases due to the presence of the open crack: for the slotted rotor, the $2\times$ amplitudes are important from $500rpm$ to $2000rpm$, whereas they are only recognisable between $1300 - 1700rpm$ for the healthy rotor.

All these results can be key indicators for the detection of open cracks in a rotating shaft.

All the previous results and comparisons between the healthy and slotted rotors are made when one-half of the shaft diameter is cracked. In real machine, it is interesting to detect small cracks when the crack depth is not greater than 10%-30% of the shaft diameter. So, to clarify the effects when the open crack is not very deep, experimental tests are done for various non-dimensional crack depths. Figures 8 show the evolutions of $1\times$, $2\times$, $3\times$, $4\times$, $5\times$ and $6\times$ amplitudes for both the vertical and horizontal directions.

First of all, the $1\times$ amplitudes increase or decrease with the increase of the transverse slot depth in both directions whereas the critical speed of the rotor system always decreases, as illustrated in Figure 8(a). The effect of slots on the critical speed of slotted rotors is consistent with the results reported by Sekhar and Srinivas [22], Pennacchi et al. [12], and Darpe et al. [13]

From the analysis of the $2\times$ and $3\times$ amplitudes in Figures 8(b) and (c), it is observed that the horizontal and vertical maximum amplitudes of the $2\times$ and $3\times$ orders growth gradually with the non-dimensional open crack depth at the $\frac{1}{2}$ and $\frac{1}{3}$ sub-critical resonant speeds, respectively. Moreover, increasing the transverse slot depth decreases the rotating speed where the $2\times$ and

$3\times$ maximum amplitudes are observed (at one-half and one-third of the first critical speed respectively). These experimental results reflect the fact that the natural frequencies of the rotor system are changed due to the reduced stiffness resulting from the transverse slot. If the open crack is not very deep (i.e. the slot is equal to $\mu = 0.4$), the $2\times$ amplitudes in the horizontal direction are twice more important than in the case of the healthy rotor as indicated in Figure 8(b). Moreover, the vertical and horizontal peaks at one-half of the rotating speed are very important and exceed $40\mu m$. Showing the evolutions of the $3\times$ amplitudes in the horizontal direction (see Figure 8(c)), the $3\times$ amplitudes appear to be four times more important than in the case of the healthy rotor. So the evolutions of the $2\times$ and $3\times$ amplitudes can be used for the detection of an open crack even if the crack is not deep. However, it can be observed that it can be difficult to detect a transverse slot that is inferior to $\mu = 0.4$ in the present study.

In regards to the $3\times$ amplitudes in Figures 8(c), it is observed that the $3\times$ amplitudes increase at $\frac{1}{2}$ sub-critical resonant speed with increasing the slot depth. As previously shown, the evolution of the $3\times$ amplitudes at $\frac{1}{2}$ sub-critical resonant speed is significant even if the transverse slot depth is not deep and is clearly recognisable if the slot depth is superior to $\mu = 0.4$ (see the horizontal direction in Figure 8(c)). However, it may be noted that the amplitudes of the $3\times$ amplitudes are small (about $4\mu m$). Consequently, the detection of variations in the $2\times$ and $3\times$ amplitudes at one-half and one-third of the first critical speeds can be used as a diagnostic tool for the detection of slotted rotor if the open crack is superior $\mu = 0.4$. We recall that the conclusions presented in this study are consistent with our test rig and limited to the case of an open crack. All the results that are presented in the study only give general tendencies for the vibration characteristics of slotted rotors. For a real machine, some researchers have demonstrated that it is possible to detect smaller cracks (14% of the diameter for the study of Pennacchi et al. [12] for example).

Finally, evolutions of the $4\times$, $5\times$ and $6\times$ harmonic components are given in Figures 8(d-f). In these cases, the increases of the $4\times$, $5\times$ and $6\times$ maximum amplitudes at $\frac{1}{4}$, $\frac{1}{5}$ and $\frac{1}{6}$ sub-critical resonant speeds are not observed or not significant enough to be used as diagnostic tools. However, it is observed that increasing the crack depth increase the $4\times$ and $5\times$ amplitudes in both the vertical and horizontal directions when the cracked rotor is passing through one-half of the first critical speed. Nevertheless, these variations are not important enough (about $1-2\mu m$) and can not be used to detect the presence of a transverse crack in rotors.

3.2.2 Influence of the slot–unbalance interaction

The main objective of the following experiments is to investigate the effects of slot-unbalance interaction on the $2\times$ and $1\times$ response amplitudes by considering variations of the unbalance orientation angle and, the amount of unbalance and the transverse slot depth.

Firstly, the effects of the slot depth and the relative angle between the slot and the unbalance for the $1\times$ maximum amplitudes when the rotor is passing through the first critical speed are shown in Figures 9(a-b) (with an unbalance of $0.4gm$). Experimental results are given for various non-dimensional slot depths in both the vertical and horizontal directions. One maxima is seen near 180° and one minima is at approximately 0° for both the vertical and horizontal directions. It can be concluded that the effects of the relative angle between the transverse slot

and the unbalance (for $0.4gm$) is more important than the effects of the slot depth (for this present study) in regards to the $1\times$ maximum amplitudes at the first critical speed. All these results are in agreement with the level of residual unbalance that has been estimated for the healthy rotor ($0.18gm$ at $168deg$). By comparing with the experimental results previously published by Darpe [13], it is noted that the variation of the peak response with phase of unbalance does not match exactly but looks similar to his case with a lower unbalance of $0.53gm$ and a slotted crack of $\mu = 0.23$.

Then, the effects of the amount of unbalance and the transverse slot depth are given in Figures 9(c-d) by keeping a phase between the unbalance and the slot front of $0deg$. It clearly appears that the amount of unbalance drastically affects the evolutions of the $1\times$ maximum amplitudes. For the healthy rotor, increasing the amount of unbalance increases the $1\times$ maximum amplitudes at the first critical speed for both the vertical and horizontal directions. This result is in agreement with the level of residual unbalance of the healthy rotor ($0.18gm$ at $168deg$). From the analysis of the evolutions of the $1\times$ maximum amplitudes for the slotted rotor in Figures 9(c) and (d), the unbalance of $0.4gm$ now gives lower responses for all the slot depths compared to the healthy rotor. The smallest horizontal and vertical amplitudes (about $40\text{--}50\mu m$) are observed for the transverse slot depth of $\mu = 0.8$. These results imply that the presence of the slot in the rotor system modifies slightly the level of residual unbalance.

Secondly, the effects of the relative angle between the transverse slot and the unbalance for the $2\times$ maximum amplitudes when the rotor is passing through one-half of the first critical speed respectively, are shown in Figures 10(a-b) for various non-dimensional crack depths (with an unbalance of $0.4gm$ at $0deg$.) in both the vertical and horizontal directions. Then, the effects of the crack depth and the amount of unbalance is given in Figures 10(c-d) (in this case the phase between the unbalance and the crack front is chosen to be $0deg$).

It is observed that for a given slot depth, the $2\times$ peak amplitudes at $\frac{1}{2}$ sub-critical resonant speed do not depend upon the angle between the unbalance and the slot front. Increase of the slot depth induces an increase of the $2\times$ amplitudes for all the slot-unbalance configurations. These results are in perfect agreement with the previous study of Mayes and Davis [15]: they observed that the $2\times$ harmonic component increases monotonically with the slot depth and that there is no variation in the $2\times$ amplitude with out-of-balance distribution. However, it can be remembered that some numerical studies [7, 19] demonstrated that the orientation between the unbalance and the crack can affect the amplitudes of the $2\times$ peak amplitudes at $\frac{1}{2}$ sub-critical resonant speed. For example, Jun et al. [19] observed an increase of the amplitude of the second harmonic components with increasing the crack depth, but they indicated that the $2\times$ harmonic components tend to have maximum or minimum amplitudes when the unbalance is in phase and out of phase with respect to the crack. As explained by Sinou [7], the intensity of unbalance is one of the key factors that can induce changes (or not) of the $2\times$ harmonic component with the orientation between the crack and unbalance.

Considering these experimental results, it can be concluded that the changes in the $2\times$ amplitudes of the rotor system through one-half of the first critical speed drastically depend on the crack depth and so appear to be the classical and robust signature for detecting the presence of an open crack in rotors.

Then, Figures 11(a) and (b) illustrate the differences between the $2\times$ maximum vertical and

horizontal amplitudes with regard to the transverse slot depth and phase between the crack and the unbalance, and the slot depth and the unbalance intensity respectively. These results demonstrate that the differences between the $2\times$ vertical and horizontal amplitudes increase monotonically with the increase of the slot depth, when the rotor is passing at one-half of the first critical speed. This phenomenon is due to the increased asymmetry as slot depth increases. These results also indicate that the effects of the slot depth are stronger than those of the unbalance intensity or those of the phase between the slot front and the unbalance.

So, for a rotor with an opened crack (with a given unbalance and phase with the crack front), not only changes in the $2\times$ amplitudes in both the vertical and horizontal directions may be used for the detection of cracks in rotors, but also differences between the $2\times$ horizontal and vertical amplitudes can be considered as one of the most practical indicators of the presence of a crack in rotors for health-monitoring purposes.

3.2.3 Orbital evolutions

Now, the attention is focused on the evolution of the orbits around one-half and one-third of the first critical speed. Firstly, the case of a rotor with a transverse slot of relative depth of $\mu = 1$ is investigated. As illustrated in Figures 12, the orbit of the slotted rotor at the middle of the shaft (plane A2) firstly changes from double loops to an outside loop (like a "eight") as the speed of the rotor increases. Then, when the rotating speed of the slotted rotor reaches through half of the first critical speed, the orbit plot changes from the outside loop to a loop containing an important loop inside with a rotation of this loop indicating a significant change in both the phase and amplitude of the $2\times$ vibration. As mentioned by Darpe et al. [13], the inner loop changes its orientation by almost 180° .

In regards to the phase evolution of the vertical and horizontal $2\times$ amplitudes of the slotted rotor (see Figure 3(d)), the rotor vibrates in a forward precession below $1340rpm$ and above $1390rpm$. So the horizontal phase leads the vertical phase and the double inside loop is present. Between $1340rpm$ and $1390rpm$, this is a reverse precession orbit and the horizontal phase lags the vertical phase as illustrated in Figure 3(d): the double outside loop appears, as shown in Figures 12. Typically, the internal loop in the direct orbit is one of the characteristic for signals containing two vibration components with the same direction of precession (see the phases of the $1\times$ and $2\times$ components in Figures 3(b) and (d)).

By comparing the evolutions of the healthy and slotted rotors' orbits (see Figures 5 and 12), it clearly appears that the presence of an open crack generates a strong evolution of the vibration characteristics of the rotor when the rotating speed passes through nearly half of the machine critical speed. Not only the maximum amplitudes of the orbits are modified, but also the size of the inner loop. In regards to the orbits of slotted rotor in Figures 12, it is shown that the speed range where the inside loop is present is larger than that of the healthy rotor (given in Figures 5). So the intensity of the inside loop can be used for the detection of an open crack in rotor.

To verify if the previous observations (variation and change of orbits around one-half of the first critical speed) are valid for deeper slot, experimental investigations with various slot depths are performed. Results are shown in Figures 13. First of all, the distortion in the two outside loops (i.e. the "eight") increases when the slot depth increases, as indicated in Figures 13 (for

the rotating speed $\omega_{rotor} = 1340rpm$). For planes A1 and A2, even if the slot depth is small (see for example the case of $\mu = 0.4$), the orbital patterns are different from the healthy rotor. Therefore, the detection of an open crack can be done by using the evolutions of the outside loops before crossing $\frac{1}{2}$ sub-critical resonance. However, the differences of the two outside loops for the different slot depths (from $\mu = 0.4$ to $\mu = 1$) are not significant enough to estimate the size of the slot.

Then, when the orbit changes from a double loop to an inside loop (i.e just before crossing $\frac{1}{2}$ sub-critical resonance), the inside loop increases with increasing the transverse slot depth for the three positions of the shaft at the left, middle and right of the rotor, as illustrated in Figures 13(d), (e) and (f) respectively (for the rotating speed $\omega_{rotor} = 1410rpm$). After crossing $\frac{1}{2}$ sub-critical resonance (at $\omega_{rotor} = 1530rpm$), Figures 13(g), (h) and (i) show that the same results are observed: increasing the slot increases monotonically the inside loop for the three planes A1, A2 and A3. This results are in perfect agreement with the numerical study of Jun et al. [19]. In regards to the orbital patterns at $\omega_{rotor} = 1410rpm$ (see Figures 13(d), (e) and (f)), it can be concluded that the vibration characteristics of the slotted rotor are different from those of the healthy rotor even if the slot depth is not deep. Moreover, the size of the inside loop is a good indicator of the slot depth. From the analysis of the evolutions of the orbital patterns from $\omega_{rotor} = 1410rpm$ to $\omega_{rotor} = 1530rpm$, it is observed that the rotation of the inside loop indicating a significant change in both the phase and amplitude of the $2\times$ vibration is recognisable and significant enough to be the signature of the presence of a transverse slot in rotor. For example, Figures 13(d) and (g) indicate that the inner loop changes its orientation by almost 180° .

Showing Figures 13(d), (e) and (f), the difference between the horizontal and vertical sizes of the inside loops increase with the increase of the slot depth. These results agree with the previous observations done in Section 3.2.2 for the evolutions and differences of the $2\times$ amplitudes in the vertical and horizontal amplitudes. So it clearly appears that the orbital changes of the inside loop can be one of the most efficient and robust signature for detecting the presence of a transverse crack in rotors.

In conclusion, all these results clearly indicate the change in both the phase and the amplitude of the $2\times$ harmonic components around one-half of the first critical speed, as previously explained in Section 3.2.1. The size of the inside loop is drastically affected by the slot depth even if the open crack is not very deep. So, the orbital movements of the rotor through the passage of one-half of the first critical speed can be used as the signature of a transverse slot in the rotor.

Now, the effects of the unbalance, and the relative orientation angle between the transverse slot and the unbalance near the rotational speeds at $\frac{1}{2}$ of the first critical speed are investigated. Figures 14(a) and (b) illustrate the orbital changes at the middle of the rotor (plane A2).

From the analysis of the orbits in Figure 14(a), it appears that the orbital evolutions with increasing the unbalance are not significant for a given slot depth (i.e. $\mu = 1$). The sizes of the inside and outside loops are practically the same for all the cases. Then, Figure 14(b) indicates that the outside and inside loops are not also drastically affected by the variation of the angle between the slot front and the unbalance. These observations can be correlated with the evolutions of the $2\times$ amplitudes of the rotor system through one-half the first critical speed,

as previously explained in Section 3.2.2.

In conclusion, the distortion of the orbit and changes of the size for the inside loop in the orbit at one-half of the first critical speed can be considered as a robust damage assessment technique for the non-destructive detection of a transverse slot.

4 Conclusion

This study presents an experimental work on the vibration characteristics of a slotted rotor that corresponds to the case of an open crack. The presence of a transverse slot in rotor induces an increase of the contributions of the $n \times$ harmonic components, and a decrease of the first critical speed and the associated $\frac{1}{n}$ sub-harmonic resonances.

It is also illustrated that the diagnosis of the presence of a slot can be based only on the evolution of the $2 \times$ harmonics response at one-half of the critical speeds. However, a reference case that is generally chosen to be the healthy rotor is needed in order to avoid a worse diagnostic since there are several other mechanisms in rotor that generate $2 \times$ amplitudes. The response of slotted rotor can be compared with those of an asymmetric rotor.

Then, a slight increase of the inside loop of orbital patterns when the rotor speed is around one-half of the first critical speed can be a key indicator for the detection of transverse slot in a rotating shaft. Moreover, the difference between the horizontal and vertical $2 \times$ amplitudes at one-half of the first critical speed appears to be a robust indicator of the presence of a slot in rotors.

So, the author hopes that the published experimental data may be useful for the future investigations of researchers that are currently working on the detection and identification of transverse open cracks in rotors. We recall that the results presented in this study can give general tendencies for the vibration characteristics of open crack rotors, but they are consistent with our test rig and limited to the case of an open crack.

Acknowledgements

The author would like to thank the financial support of the Centre National de la Recherche Scientifique and the laboratory LTDS UMR-CNRS 5513 (Laboratoire de Tribologie et Dynamique des Systèmes, Unité Mixte de Recherche du Centre National de la Recherche Scientifique 5513) to carry out this research.

References

- [1] Wauer, J., 1990. “Dynamics of cracked rotors: Literature survey”. *Applied Mechanics Review*, **43**, pp. 13–17 .
- [2] Dimarogonas, A., 1996. “Vibration of cracked structures: a state of the art review”. *Engineering Fracture Mechanics*, **55**, p. 831–857.

-
- [3] Sabnavis, G., Kirk, R. G., Kasarda, M., and Quinn, D., 2004. "Cracked shaft detection and diagnostics: A literature review". *The Shock and Vibration Digest*, **36**(4), pp. 287–296.
- [4] Darpe, A., Gupta, K., and Chawla, A., 2006. "Dynamics of a bowed rotor with a transverse surface crack". *Journal of Sound and Vibration*, **296**, p. 888–907.
- [5] Sinou, J.-J., and Lees, A. W., 2005. "Influence of cracks in rotating shafts". *Journal of Sound and Vibration*, **285**(4-5), pp. 1015–1037.
- [6] Sinou, J.-J., and Lees, A. W., 2007. "A non-linear study of a cracked rotor". *European Journal of Mechanics A/Solids*, **26**(1), pp. 152–170.
- [7] Sinou, J.-J., 2008. "Detection of cracks in rotor based on the 2x and 3x super-harmonic frequency components and the crack-unbalance interactions". *Communication in Non-linear Sciences and Numerical Simulation*, **13**, p. 2024–2040.
- [8] Seibold, S., and Weiner, K., 1996. "A time domain method for the localization of cracks in rotors". *Journal of Sound and Vibration*, **195**(1), pp. 57–73.
- [9] Darpe, K., Gupta, K., and Chawla, A., 2003. "Experimental investigations of the response of a cracked rotor to periodic axial excitation". *Journal of Sound and Vibration*, **260**(2), pp. 265–286.
- [10] Bachschmid, N., Pennacchi, P., Tanzi, E., and Vania, A., 2000. "Identification of transverse crack position and depth in rotor systems". *Meccanica*, **35**, p. 563–582.
- [11] Bachschmid, N., Pennacchi, P., and Vania, A., 2002. "Identification of multiple faults in rotor systems,". *Journal of Sound and Vibration*, **254**(2), pp. 327–366.
- [12] Pennacchi, P., Bachschmid, N., and Vania, A., 2006. "A model-based identification method of transverse cracks in rotating shafts suitable for industrial machines". *Mechanical Systems and Signal Processing*, **20**, p. 2112–2147.
- [13] Darpe, A., Gupta, K., and Chawla, A., 2004. "Transient response and breathing behaviour of a cracked jeffcott rotor". *Journal of Sound and Vibration*, **272**, p. 207–243.
- [14] Adewusi, S., and Al-Bedoor, B., 2002. "Experimental study on the vibration of an overhung rotor with a propagating transverse crack". *Shock and Vibration*, **9**, p. 91–104.
- [15] Davies, W. G. R., and Mayes, I. W., 1984. "The vibrational behaviour of a multi-shaft, multi-bearing system in the presence of a propagating transverse crack". *Transactions of the ASME Journal of Vibration, Acoustics, Stress, and Reliability in Design*, **106**, pp. 146–153.
- [16] Mayes, I. W., and Davies, W. G. R., 1984. "Analysis of the response of a multi-rotor-bearing system containing a transverse crack in a rotor". *Transactions of the ASME Journal of Vibration, Acoustics, Stress, and Reliability in Design*, **106**, pp. 139–145.

-
- [17] Taylor, H., 1940. "Critical speed behaviour of unsymmetrical shafts". *Journal of Applied Mechanics*.
- [18] Henry, T., and Okah, B., 1976. "Vibration in cracked shafts". *IMechE Conference on Vibrations in Rotating Machinery*, **C/162/76**, p. 15–19.
- [19] Jun, O., Eun, H., Earmme, Y., and Lee, C., 1992. "Modelling and vibration analysis of a simple rotor with a breathing crack". *Journal of Sound and Vibration*, **155(2)**, pp. 273–290.
- [20] Plaut, R., Andruet, R., and Suherman, S., 1994. "Behaviour of a cracked rotating shaft during passage through a critical speed". *Journal of Sound and Vibration*, **173**, pp. 577–589.
- [21] Bachschmid, N., Pennacchi, P., Tanzi, E., and Audebert, S., 2003. "Transverse crack modeling and validation in rotor systems, including thermal effects". *International Journal of Rotating Machinery*, **9(2)**, pp. 113–126.
- [22] Sekhar, A. . S., and Srinivas, B. N., 2002. "Vibration characteristics of slotted shafts". *Journal of Sound and Vibration*, **251(4)**, pp. 621–630.

Figure 2: Evolution of $n\times$ amplitudes and phase in plane A2 for the healthy and slotted rotors ($\mu = 1$) with the initial residual unbalance (a) $1\times$, healthy rotor (b) $1\times$, slotted rotor (c) $2\times$, healthy rotor (d) $2\times$, slotted rotor (e) $3\times$, healthy rotor (f) $3\times$ slotted rotor (solid lines = horizontal direction, dashed lines = vertical direction)

Figure 3: Evolution of $n \times$ amplitudes and phase in plane A2 for the healthy and slotted rotors ($\mu = 1$) with the unbalance of $1gm$ at $0deg$. (a) $1 \times$, healthy rotor (b) $1 \times$, slotted rotor (c) $2 \times$, healthy rotor (d) $2 \times$, slotted rotor (e) $3 \times$, healthy rotor (f) $3 \times$ slotted rotor (solid lines = horizontal direction, dashed lines = vertical direction)

Figure 4: Evolution of the global response, 1 $\times$, 2 $\times$ and 3 $\times$ amplitudes for the healthy and slootted rotors ($\mu = 1$) with an unbalance of 1gm and a phase between the unbalance and the crack front of 0 degree. (a-b) plane A1 (c-d) plane A3 (solid lines = uncracked rotor, dashed lines = cracked rotor, black = global amplitudes, blue = 1 $\times$, green= 2 $\times$, red = 3 $\times$)

Figure 5: Orbital evolutions for the healthy rotor for the plane A2 around one-half of the first critical speed with an unbalance of 1gm and a phase between the unbalance and the crack front of 0 deg.

Figure 6: Evolutions of the n^{th} orders for the healthy rotor with an unbalance of 1gm and a phase between the unbalance and the crack front of 0 deg.

Figure 7: Evolutions of the n^{th} orders for the slotted rotor with $\mu = 1$ (unbalance = 1 gm, phase between the unbalance and the slot front = 0 deg.)

Figure 8: Evolutions of the $n \times$ amplitudes for various crack depths with an unbalance of 1gm and a phase between the unbalance and the slot front of 0 deg. (a) $1 \times$ - plane A2, (b) $2 \times$ - plane A2, (c) $3 \times$ - plane A1, (d) $4 \times$ - plane A3, (e) $5 \times$ - plane A1, (f) $6 \times$ - plane A3 (-o- uncracked, -+- $\mu = 0.2$, -.- $\mu = 0.4$, $\cdots$ $\mu = 0.6$, - - $\mu = 0.8$, - $\mu = 1$)

a

b

c

d

Figure 9: Evolutions of the $1 \times$ maximum amplitudes at the first critical speed for the horizontal and vertical directions at the plane 2 (a,b) versus the slot depth and the phase between the unbalance and the slot front for an unbalance of 0.4gm (c,d) versus the slot depth and the unbalance with a phase between the unbalance and the slot front of 0 deg.

Figure 10: Evolutions of the $2\times$ maximum amplitudes at one-half of the first critical speed for the horizontal and vertical directions at the plane 2 (a,b) versus the slot depth and the phase between the unbalance and the slot front for an unbalance of 0.4gm (c,d) versus the slot depth and the unbalance with a phase between the unbalance and the slot front of 0 deg.

a

b

Figure 11: Differences between the horizontal and vertical directions of the $2\times$ maximum amplitudes at one-half of the first critical speed on plane A2 (a) for various crack depths and unbalance with a phase of 0 deg. (b) for various crack depths and phases between the unbalance and the crack front with an unbalance of 0.4gm

Figure 12: Orbital evolutions of the cracked rotor for plane A2(with $\mu = 1$) around one-half of the first critical speed with an unbalance of 1gm and a phase between the unbalance and the crack front of 0 deg.

Figure 13: Orbits of the cracked rotor around one-half of the first critical speed with an unbalance of 1gm and a phase between the unbalance and the crack front of 0 deg. (red: $\mu = 1$, magenta: $\mu = 0.8$, blue: $\mu = 0.6$, black: $\mu = 0.4$). (a) Plane A1 - $\omega_{rotor} = 1340rpm$, (b) Plane A2 - $\omega_{rotor} = 1340rpm$, (c) Plane A3 - $\omega_{rotor} = 1340rpm$, (d) Plane A1 - $\omega_{rotor} = 1410rpm$, (e) Plane A2 - $\omega_{rotor} = 1410rpm$, (f) Plane A3 - $\omega_{rotor} = 1410rpm$, (g) Plane A1 - $\omega_{rotor} = 1530rpm$, (h) Plane A2 - $\omega_{rotor} = 1530rpm$, (i) Plane A3 - $\omega_{rotor} = 1530rpm$

Figure 14: Changes in the orbital patterns at the one-half of the first critical speed as a function of (a) the phase with $\mu = 1$ and an unbalance of $1gm$ (red: 0 deg., magenta: 90 deg., blue: 180 deg., black: 270 deg.), (b) the unbalance with $\mu = 1$ and a phase of 0 deg. (black: $0gm$, blue: $0.4gm$, magenta: $0.8gm$, red: $1gm$)